

# QDec Measurement Summary

## Measurement Information




<b>Panel:</b>	Helio_BM37	<b>Meas. Date:</b>	05.10.2016 - 20:42:38
<b>Paneltype:</b>	Heliostat	<b>Operator:</b>	DLR Expert User
<b>Setup:</b>	MeasPosition	<b>Comment:</b>	
<b>Negl. Rim:</b>	0 mm	<b>System:</b>	QDec_2014-101
<b>Orientation:</b>	Mean Slope to Zero	<b>Location:</b>	Jülich

## Result Overview

**Quality:** no specifications      Evaluated Surface: 81.2 %

Value	Measurement	Specification	Description
SDx	1.60 mrad		Slope deviation in x-direction (rms)
SDy	1.51 mrad		Slope deviation in y-direction (rms)
ICAP_D1	85.72 %		Intercept on aperture

## Result Graphs



## Measurement System Information

Config File:	130929_Helio	QDec Version:	3.1.3680 (14.05.2014)
Evaluation Date:	13.10.2016 - 10:06:43		
Last Calibration:	14.08.2014		
PDF Filename:	...\MeasData_161005\Results\Helio\Helio_BM37\Helio_BM37_Rim0_Result_161013100643.pdf		